

HSM Risk Assessment

Vince's Cross - Hut Point, Ross Island

[i](#) DETAILS

Shared 2026-03-21
Created 2025-01-29 15:42:56
Owner guest

Description

Cross at Hut Point, Ross Island, erected in February 1904 by the British Antarctic Expedition of 1901-04, in memory of George Vince, a member of the expedition, who died in the vicinity.

Risk Assessment Score

7.7

0 (Low)

10 (Extreme)

Risk Assessment Details

1 Is the HSM comprised of durable materials? **No**

2 Is the HSM located in the Western Antarctic (i.e., west of the Transantarctic Mountains)? **Yes**

3 Is the HSM located on the Antarctic Peninsula, South Orkney Islands, or South Shetland Islands? **No**

4 Is the HSM located at a coastal site? **Yes**

5 Is the HSM located 3m or less above sea level? **No**

6 Is the HSM located within 100m of shoreline? **Yes**

7 Does the HSM site have steep slopes (i.e., greater than 20%)? **Yes**

8 Is the HSM situated on permafrost soils? **Yes**